



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
July 27

Repair Work

Devil's Slide (post mile 39.14)

- Paving work was completed today.



- Excavation work started to provide access for drilling into the cliff below the road to install horizontal drains.



Creating access for drain work



- Yerba Buena Construction continued with erosion control work.



Securing the erosion control fabric today



Slide Location No. 3 (post mile 39.77)

- Construction of the retaining wall at this location continued. H-beams are being installed.



Drilling for H-beam installation



H-beams installed